## **Application for fitness Certificate of School Buildings**

(To be filled by the Manager) LOURDES PUBLIC SCHOOL, KOTTAYAM Name of the School 1. Location with names of Educational Dist/Sub Dist 2. KOTTAYAM 13sued dated 19/06/2024 Whether fitness Certificate has been issued in 3. previous years and if so the number and date Kottayam Municipality of the last Certificate and the authority who issued it Classification of the building and size - 443, 75 89,M 1. Basement Floor (basis for classification) - 1611. 93 sqm Ground Flood I. Permanent (Single or Multi-storeyed) - 1590.49 Sam Fiast Flood 4. Second Floor - 1590.49 Sam II. Semi-permanent 5. Third Floor - 1590. 49 89m III. Temporary shed 1997, 2000, 2012, 2017 5. Year of construction of different buildings Permanent multi Storaged 6. **Short specifications** 7. Foundation and Basement. RCC column Footing and beams (i) Rubble in lime mortar/Mud mortar/ Cement mortar or Laterite in lime Mortar/Cement mortar/Mud mortar Rubble In cement Morted (ii) Superstructure

Rubble in lime, cement mud or brick, laterite in lime, mud or brick in lime for pillars with Intermediate walls with sun dried bricks

oubble / Boick mostar cement cement

(iii) Doors and windows Country wood (mention species)

Anjaliwood

- (iv) Wood work wrought and put up country wood (mentions species) full or half bamboo for rafters iron trusses.
- Trafford (v) Kind of roof with short specifications of materials used /RCC/ tiled thatched / A.C. Sheets.
- (vi) Flooring Cement plastered, Hard broken stone concrete bedding gravel concrete laterite chips or cow dung washed.

cement plustered and ceramic Tiles.

8. Whether regular attended to or not. Period during Which last maintenance was done.

yes

1 Fr. Jacob Vactackatty Cherian solemnly declare that the above details furnished are correct to the best of my knowledge.

Place: Kottayan Date:

COLLECTORATE P.O. KOTTAYAM-2

## To be filled by the Inspecting Officer – Junior Engineer

- Riya Rachel Eypc 1. Name of the Officer 2025-2026 2. Period for which Certificate is issued 3. Nature of defect if any
- Cellar Hoor = 443.7 m2 Nu. Ground Ploor = 1611.93 m²

  First floor = 1590-49 m²

  Second Ploor = 1590.49 m² a) Foundation and Basement b) Superstructure c) Doors and Windows
- Thurd flow = 1590:49m2 d) Roof
- f) Miscellaneous (Cracks and C)
- 4. Any Major defects noticed which will render the building unsafe in any manner
- 5. Whether maintenance works have been done properly
- 6. Whether the structure is sound or not for conducting Yes, The Brueture is sained classes for conducting classes under normal weather condition

## Note:

e) Flooring

- The stability of the structure should be examined also with the reference to location attitude, intensity of wind Exposure of flood etc.
- 2. Any additional observation it deemed necessary for the certificate may be furnished separately with the certificate

For the reason stated above.

Date: 17/07/2025

MANAGER LOURDES PUBLIC SCHOOL

ATTEST

Signature

Designation

Lourdes Public School Kattauam.